

TECHNICAL IMPROVEMENT PROGRAM

TIP-10051

Machine Model for the Improvement:

AutoMax and EM

Description of Improvement:

This option eliminates all linkage on top of butterfly. Provides a more reliable and simplified option



For further details do not hesitate to contact us:

Tel.: (715) 341-6501

Fax: (715) 345-1004

E-Mail: info@automatan.com

Web: www.automatan.com

Please note!

These statements are for general information. We are pleased to make you a detailed offer, based on an inspection of your machine.

Less manual labor – increased profit margins!